North America Emission Control Area Fuel Oil Non-Availability Report
ECA0100
1 2 2 3
##

##(Include Double Pound for comments not form fields)
##Report Form ID Ship Operator Name Oldendorff Wandarin Hantong

4 5 6 7

Flag Country IMO ID Number Date of ECA First Notice Location of ECA First Notice Singapore 9569956 12-Feb-14 At sea 1 day before arrival Durban

Name of Ports after First Notice Name of Last Port before ECA Entry Durban Richards Bay

Name of Port with Fuel Oil Supply Disruption Richards Bay Name of Original Fuel Supplier with Disruption BP & Shell

12 13 14

Number of Fuel Suppliers Contacted Date of Entry in the ECA Time of Entry in the ECA 27-Mar-14

15 16 17

Sulfur Content of Non-Compliant Fuel Oil Projected Hours on Main Propulsion Name of First POC 2.48% 29Hrs New Orleans

Compliance Fuel Oil Available at First POC? Plan to Bunker Compliant Fuel Oil at First POC? Yes

20 21 22

Number of fuel suppliers contacted at First POC Name of Second POC Compliant Fuel Oil at Second POC? Lake Charles Yes

Plan to Bunker Compliance Fuel Oil at Second POC? Number of Fuel Suppliers Contacted at the Second POC? No

Date of Exit from ECA? Time of Exit from ECA? Has this vessel operated in the ECA in previous 12 months?

15-Apr-14 No

27

Number of Submitted Reports Designated Corporate Official Name Designated Corporate Official E-mail Dasin Shipping Pte Ltd Designated Corporate Official E-mail Designated Corporate Official E-mail Designated Corporate Official E-mail Designated Corporate Official E-mail Designated Corporate Official Name Designated Official Name Designated Corporate Official Name Designated Corporate Official Name Designated Corporate Official Name

Designated Corporate Official Phone Number Description of Actions to Achieve Compliance 6562219168